

Standing water inside the impoundments (bathtub effect)



Exposed sludge eroding to the river



Exposed sludge and surface water runoff (discolored)



Exposed Sludge erosion (discolored)



Exposed sludge



Bathtub effect inside impoundments



Trash in impoundment from overtopping river water



Trash on berms



Discolored runoff water on exposed sludge – apparent animal tracks



Trash overtopping berms



Abandoned railroad ties



Animal carcass between river and impoundment

